

## County Surveyor's Record, Douglas County, Oregon

74

## Extensions Survey of Subdivisions of T. 27 S., R. 2 W., W.M.

CHAINS

- 40.00 Set a Hemlock Post 3 ft. long, 4 ins. sq., 24 ins. in the ground for  $\frac{1}{4}$  sec. cor., marked  $\frac{1}{4}$  S 29 on North and 32 on South faces from which
- A Cedar, 12 ins. diam., bears N.50°E., 17 lks. dist.  
Marked  $\frac{1}{4}$  S 29 B T
- A Cedar, 6 ins. diam., bears S.36°30'W., 29 lks. dist.,  
Marked  $\frac{1}{4}$  S 32 B T
- 41.00 Derricks  $\frac{1}{4}$  sec. cor., which I now destroy, bears North 350 lks. dist.
- 50.50 Creek, 3 lks. wide, course NW
- 52.20 Creek, 2 lks. wide, course NE
- Ascend ridge, through heavy timber and dense undergrowth
- 80.00 Set a Cedar Post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for cor. of secs. 29, 30, 31 & 32, marked T 27 S S 29 on NE., R 2 W S 32 on SE., S 31 on SW., and S 30 on NW face, with one notch on South and 5 notches on E edge from which
- A Cedar, 30 ins. diam., bears N.42°30'E., 63 lks. dist.  
Marked T 27 S R 2 W S 29 B T
- A Cedar, 12 ins. diam., bears S.63°30'E., 29 lks. dist.  
Marked T 27 S R 2 W S 32 BT
- A Hemlock, 24 ins. diam., bears S.48°W., 12 lks. dist.  
Marked T 27 S R 2 W S 31 B T
- A Hemlock, 8 ins. diam., bears N.5°W., 47 lks. dist.  
Marked T 27 S R 2 W S 30 B T
- Derricks cor. for secs. 29, 30, 31 & 32 which I now destroy bears N.64°30'W., 320 lks. dist.
- Land Mountainous
- Soil, 1st. and 2nd. rate
- Timber, Fir, Hemlock, Cedar and Pine
- Dense undergrowth of little Fir, Hemlock and Vinemaple.
- Mountainous land, covered with heavy timber and dense undergrowth, and exceptionally difficult to survey. 80.00 chs.

Sky overcast at noon; lat. observation impossible

October 9, 1911