

76

Extension Survey of Subdivisions of T. 27 S., R. 2 W., W.M.

CHAINS

At the cor. of secs. 29, 30, 31 & 32

Thence I run

West, on Sectional Correction Line, bet. secs. 30 & 31

Descend steep slope, through dense timber and underbrush
exceptionally difficult to survey

9.80 Blazed trail bears N & S

10.75 Creek, 2 lks. wide, course NE

15.25 Cabin, bears North 50 lks. dist.

19.85 Old horse trail bears NE & SW

23.00 Top of ridge, bears NW and SE

40.00 Set a Hemlock Post, 3 ft. long, 4 ins. sq., 24 ins. in the
ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S 30 on North and 31 on
South face from which

A Hemlock, 30 ins. diam., bears N.46*W., 19 lks. dist.

Marked $\frac{1}{4}$ S 30 B T

A Chinquapin, 6 ins. diam., bears S.66*50'W., 23 lks.
dist., Marked $\frac{1}{4}$ S 31 B T

42.85 Derricks $\frac{1}{4}$ sec. cor. which I now destroy, bears North 130
lks. dist.

43.90 Creek, 3 lks. wide, course NW

50.10 Creek, 3 lks. wide, course NW

83.70 Intersect East boundary of Township 27 S., R. 3 W., 200
lks. S. 0*16'W., of the cor. of secs. 25 & 36

At Point of intersection, Set a Hemlock Post, 3 ft. long
4 ins. sq., 24 ins. in the ground for closing cor. of
secs. 30 & 31 marked C C T 27 S R 2 W on E., S 31 on S.,
and S 30 on North with 1 groove on South and 5 grooves
on North face from which

A Fir, 36 ins. diam., bears N.50*E., 28 lks. dist.,

Marked T 27 S R 2 W S 30 B T

A Fir, 36 ins. diam., bears S.75*E., 29 lks. dist.,

Marked T 27 S R 2 W S 31 B T

Land Mountainous

Soil, 1st. and 2nd. rate

Timber, Fir, Hemlock, Cedar and Pine

Dense undergrowth of little Fir, Hemlock and Vinemaple

This is from a hand written note, in red, on the
 scanned copy of the orig. line notes on the internet
 (OR-R0483 PG 0364.000) The following is the note:
 "This cor. refers to Sec. 30 only" (See G.L.O. Letter
 "E" 311250 JB dated Sept. 10, 1913)
 added 9/18/2008 DCSO JC