

County Surveyor's Record, Douglas County, Oregon

76

Extension Survey of Subdivision of T. 27 S., R. 2 W., W.M.

CHAINS

Mountainous land, covered with heavy timber and dense undergrowth and exceptionally difficult to survey. 83.70 chs.
Sky overcast at noon; lat. observation impossible

October 10, 1911.

At the cor. of secs. 26, 27, 34 and 35

Thence I run

S.0°02'E., bet. secs. 34 & 35

Ascend steep slope, through dense timber and underbrush exceptionally difficult to survey

12.35 Ridge, course E & W; Descend

26.90 Creek, 2 lks. wide, course East

34.20 Cabin, bears East, 5 chs. dist.

40.00 Set a Cedar Post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S 34 on W., and 35 on E faces from which

A Fir, 18 ins. diam., bears S.40°10'E., 79 lks. dist.

Marked $\frac{1}{4}$ S 35 B T

A Hemlock, 24 ins. diam., bears S54°40'W., 63 lks.

dist., Marked $\frac{1}{4}$ S 34 B T

No trace of Derricks $\frac{1}{4}$ sec. cor. can be found after diligent search

74.55 A deserted Cabin, bears East 3 chs. dist.

A deserted cabin, bears West 3 chs. dist.

77.55 Intersect South boundary of township 220 lks. S.87°07'E. of old cor. of secs. 34 and 35 which I have previously changed to an angle point

At point of intersection, I set a Fir Post, 3 ft. long 4 ins. sq., 24 ins. in the ground for closing cor. of secs, 34 and 35 marked CC T 27 S R 2 W on N., S 35 on E., And S 34 on W., with 2 grooves on E and 4 grooves on W face from which

A Cedar, 30 ins. diam., bears N.45°E., 11 lks. dist.,

Marked T 27 S R 2 W S 35 B T

A Fir, 36 ins. diam., bears N.78°W., 92 lks. dist.,

Marked T 27 S R 2 W S 34 B T

Land Mountainous