

Extensions Survey of Subdivisions of T. 27 S., R. 2 W., N.M.

CHAINS

Soil, 1st. and 2nd. rate

Timber, heavy Fir, Hemlock, Cedar and Pine

Dense undergrowth, little Fir, Hemlock and Vinemaple

Mountainous land, covered with heavy timber and dense undergrowth and exceptionally difficult to survey.

77.55 chs.

Sky overcast at noon; lat. observation impossible

October 11, 1911

At the cor. of secs. 26, 27, 34 & 35

Thence I run

N.0°02'W., bet. secs. 26 & 27

Descend ridge, through heavy timber and dense undergrowth exceptionally difficult to survey

8.75 Creek, 1 lk. wide, course East

38.00 Cabin bears West, 2 chs. dist.

40.00 Set a Hemlock Post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S 27 on W., and 26 on East face from whichA Hemlock, 12 ins. diam., bears S.26°40'E., 29 lks. dist., Marked $\frac{1}{4}$ S 26 B TA Hemlock, 18 ins. diam., bears N.57°10'W., 12 lks. dist., Marked $\frac{1}{4}$ S 27 B TDerricks $\frac{1}{4}$ sec. cor. which I now destroy, bears N.26°40'E., 4.50 chs. dist.

41.00 Main settlers and Rangers trail to Red butte, bears North and SE.

45.00 Creek, 1 lk. wide, course NE

73.00 Leave Rangers trail bears NE & South

79.00 Branch trail to sec. 28, bears E & W.

80.00 A Hemlock Tree, 24 ins. diam., for cor. of secs. 22, 23, 26 & 27, I mark T 27 S S 23 on NE., R 2 W S 26 on SE., S 27 on SW., and S 22 on NW sides, with 2 notches on South and East edges from which

A Fir, 36 ins. diam., bears N.4°E., 57 lks. dist., Marked T 27 S R 2 W S 23 B T