

Extension Survey of Subdivisions of T. 27 S., R. 2 W., W.M.

CHAINS	exceptionally difficult to survey.
2.85	Top of rocky ridge, bears E & W; Descend
8.35	Canyon, course NW; Ascend
20.35	Old Blazed trail to Peel and Red Butte, bears NE and SW
39.00	Top of ridge, bears N & S
45.00	Derricks $\frac{1}{2}$ sec. cor. which I now destroy, bears East, 25 lks. dist.
50.35	Set a Maple Post, 3 ft. long, 3 ins. sq., 24 ins. in the ground for $\frac{1}{2}$ sec. cor. marked $\frac{1}{2}$ S 15 on W. and 14 on E. faces from which A Yew, 10 ins. diam., bears N.20*E., 58 lks. dist., Marked $\frac{1}{2}$ S 14 B T A Maple, 6 ins. diam., bears S.39*W., 22 lks. dist., Marked $\frac{1}{2}$ S 15 B T
66.05	Main trail to Peel and Red Butte, course NW and SE
90.35	Cor. of secs. 14, 15, 22 & 23 Land Mountainous Soil, 1st. and 2nd. rate Timber, Heavy Fir, Hemlock, Cedar and Pine Dense undergrowth of little Fir, Hemlock, Cedar and Pine Mountainous land, covered with heavy timber and dense under- brush and exceptionally difficult to survey. 90.35 chs. The sky was overcast at noon; observation for lat. im- possible. October 15, 1911
	At the cor. of secs. 27, 28, 33 & 34 Thence I run S.0*02'E., bet. secs. 33 and 34 Ascend steep slope, through dense timber and underbrush exceptionally difficult to survey
27.00	Top of rocky ridge bears NE and SW; Descend
34.00	Wash, course NW; Ascend
40.00	Set Hemlock Post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for $\frac{1}{2}$ sec. cor., marked $\frac{1}{2}$ S 33 on W., and 34 on