

63

Extension Survey of Subdivisions of T. 27 S., R. 2 W., W.M.

CHAINS	<p>East face from which</p> <p style="padding-left: 40px;">A Fir, 10 ins. diam., bears N.47*50'E., 63 lks. dist., Marked $\frac{1}{2}$ S 34 B T</p> <p style="padding-left: 40px;">A Fir, 12 ins. diam., bears S.11*50'W., 123 lks. dist., Marked $\frac{1}{2}$ S 33 B T</p> <p>Derricks $\frac{1}{2}$ sec. cor., which I now destroy, bears N.22*E., 310 lks. dist.</p> <p>41.00 Top of ridge, bears NW and SE</p> <p>78.40 Intersect South boundary, Tp. 265 lks. N.87*57'E., of old cor. for secs. 33 & 34 which I have previously changed to an angle point.</p> <p>At point of intersection, I set a Fir Post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for closing cor. of secs. 33 & 34, marked C C T 27 S R 2 W on N., S 33 on W., and S 34 on E., with 3 grooves on E., and W. faces from which</p> <p style="padding-left: 40px;">A Hemlock, 14 ins. diam., bears N.1*30'E., 66 lks. dist., Marked T 27 S R 2 W S 34 B T</p> <p style="padding-left: 40px;">A Fir, 40 ins. diam., bears N.42*30'W., 40 lks. dist. Marked T 27 S R 2 W S 33 B T</p> <p>Land Mountainous</p> <p>Soil, 1st. and 2nd. rate</p> <p>Timber, heavy Fir, Hemlock, Cedar and Pine</p> <p>Dense undergrowth, little Fir, Hemlock and Vinemaple</p> <p>Mountainous land, covered with heavy timber and dense underbrush and exceptionally difficult to survey. 78.40 chains</p> <hr/> <p>From the cor. of secs. 27, 28, 33 & 34</p> <p>I run</p> <p>N.0*02'W., bet. secs. 27 & 28</p> <p>Ascend ridge, through heavy timber and dense undergrowth exceptionally difficult to survey</p> <p>22.00 Top of ridge, bears NW and SE; Descend ridge, through heavy timber and brush</p> <p>26.35 Creek, 10 lks. wide, course NW</p>
--------	--