

Extensions Survey of Subdivisions of T. 27 S., R. 2 W., W.M.

CHAINS

- 33.00 Cabin bears West 150 lks. dist.
- 40.00 Set Dogwood Post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S 28 on W., and 27 on E faces from which
- A Fir, 24 ins. diam., bears N.84*30'E., 22 lks. dist.,
Marked $\frac{1}{4}$ S 27 B T
- A Fir, 35 ins. diam., bears S.31*W., 53 lks. dist.,
Marked $\frac{1}{4}$ S 28 B T
- 43.50 Derricks $\frac{1}{4}$ sec. cor., which I now destroy, bears E. 20 lks. dist.
- 56.00 Creek, 3 lks. wide, course West
- 59.00 Trail bears E & W
- 64.00 Top of ridge bears E & W
- 80.00 Set a Cedar Post, 3 ft. long 4 ins. sq., 24 ins. in the ground for cor. of secs. 21, 22, 27 & 28, marked T 27 S S 22 on NE., R. 2 W S 27 on SE., S 28 on SW., and S 21 on NW. faces with 2 notches on South and 3 notches on E edges from which
- A Fir, 24 ins. diam., bears N.68*40'E., 75 lks. dist.,
Marked T 27 S R 2 W S 22 B T
- A Fir, 12 ins. diam., bears S.68*E., 46 lks. dist.,
Marked T 27 S R 2 W S 27 B T
- A Fir, 10 ins. diam., bears S.15*W., 40 lks. dist.,
Marked T 27 S R 2 W S 28 B T
- A Hemlock, 24 ins. diam., bears N.31*30'W., 31 lks. dist.,
Marked T 27 S R 2 W S 21 B T
- Derricks cor. for secs. 21, 22, 27 & 28 which I now destroy bears North 405 lks. dist.
- Land Mountainous
- Soil, 1st. and 2nd. rate
- Timber, heavy Fir, Hemlock, Cedar and Pine
- Dense undergrowth, little Fir, Hemlock and Vinemaple
- Mountainous land, covered with heavy timber and dense undergrowth and exceptionally difficult to survey. 80.00 chs.
- Sky overcast at noon; lat. observation impossible