

County Surveyor's Record, Douglas County, Oregon

Extension Survey of Subdivisions of T. 27 S., R. 2 W., W.M.

CHAINS	<p>Dense undergrowth little Fir, Hemlock, and Vinemaple Mountainous land, covered with heavy timber and dense undergrowth and exceptionally difficult to survey.</p> <p>80.05 chs.</p> <p style="text-align: right;">October 17, 1911</p>
	<p>At the cor. of secs. 21, 22, 27 & 28</p> <p>Thence I run</p> <p>N.0°02'W., bet. secs. 21 & 22</p> <p>Descend through heavy timber and dense undergrowth, exceptionally difficult to survey.</p>
9.90	<p>Creek, 3 lks. wide, course NE</p> <p>Ascend ridge, through heavy timber and brush</p>
37.00	<p>Top of ridge bears E & W</p>
40.00	<p>Set a Fir Post, 3 ft. long 4 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S 21 on W., and 22 on E faces from which</p> <p style="padding-left: 40px;">A Fir, 12 ins. diam., bears S.89°E., 51 lks. dist., Marked $\frac{1}{4}$ S 22 B T</p> <p style="padding-left: 40px;">A Fir, 24 ins. diam., bears N.89°W., 52 lks. dist., Marked $\frac{1}{4}$ S 21 B T</p>
44.76	<p>Derricks $\frac{1}{4}$ sec. cor., which I now destroy, bears E. 29 lks. dist.</p> <p>Ascend over plateau, through heavy timber and brush</p>
80.00	<p>Set a Fir Post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for cor. of secs. 15, 16, 21 & 22, marked T 27 S S 15 on NE., R 2 W S 22 on SE., S 21 on SW., and S 16 on NW. faces with 3 notches on S and E edges from which</p> <p style="padding-left: 40px;">A Cedar, 24 ins. diam., bears N.68°E., 201 lks. dist., Marked T 27 S R 2 W S 15 B T</p> <p style="padding-left: 40px;">A Cedar, 18 ins. diam., bears S.25°E., 70 lks. dist., Marked T 27 S R 2 W S 22 B T</p> <p style="padding-left: 40px;">A Fir, 12 ins. diam., bears S.19°W., 71 lks. dist., Marked T 27 S R 2 W S 21 B T</p> <p style="padding-left: 40px;">A Fir, 30 ins. diam., bears N.52°40'W., 102 lks. dist., Marked T 27 S R 2 W S 16 B T</p>