

County Surveyor's Record, Douglas County, Oregon

95

Extension Survey of Subdivision of T. 27 S., R. 2 W. W.M.

CHAINS

Undergrowth and exceptionally difficult to survey.
80.25 chains.

October 22, 1911.

At the cor. of Secs. 16, 17, 20 and 21.

Thence I run

N.0°03'W., bet. Secs. 16 and 17.

Ascend steep slope, through dense timber and underbrush, exceptionally difficult to survey.

25.70 Top of ridge, bears NW and SE; descend.

40.00 Set Hemlock post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for $\frac{1}{4}$ Sec. cor. marked $\frac{1}{4}$ S 17 on W and 16 on E faces, from which

A Hemlock, 12 ins. diam., bears S.3°20'E., 30 lks. dist., marked $\frac{1}{4}$ S 16 B T.

A Hemlock, 10 ins. diam., bears S.70°30'W., 17 lks. dist., marked $\frac{1}{4}$ S 17 B T.

Am unable after diligent search to find Derricks $\frac{1}{4}$ Sec. corner.

Ascend through heavy timber and dense underbrush.

68.95 Rim rock, 40 ft. high, bears E and W.

71.20 Top of ridge, bears E and W; descend.

76.90 Creek, 3 lks. wide, course E; ascend.

83.35 Top of ridge, bears SE and NW; descend through timber and dense underbrush.

89.20 Intersect S boundary of Sec. 9, 386 lks. N.89°35'E., of cor. of Secs. 8 and 9. At point of intersection I set a Fir post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for closing cor. of Secs. 16 and 17, marked C C T 27 S R 2 W on S., S 16 on E., S 17 on W face; with 2 grooves on W and 4 grooves on E face, from which

A Fir, 28 ins. diam., bears S.16°10'E., 7 lks. dist., marked T 27 S R 2 W S 16 B T.