

107

Retracement and Resurvey of Sixth Standard Parallel S.,
through R. 2 W.

CHAINS

A Fir, 48 ins; diam., bears S.28°E., 212 lks. dist.,

Marked $\frac{1}{2}$ S 1 B T

A Fir, 84 ins. diam., bears S.43°W., 75 lks. dist.,

Marked $\frac{1}{2}$ S 1 B T

16.10 Trail to Red Butte Lookout, bears NE & SW

23.50 Leave living timber, enter old burn, bears NW and SE

27.50 Spur, slopes NW., Descend 175 ft. over W. slope

39.57 The Standard corner of secs. 35 & 36 which is a sound Fir Post, 4 ins. sq., 12 ins. above ground, properly marked. This is evidently not the original corner established by Flint and appears to have been set at the time of the Wygant resurvey of this line, though not shown in the notes. From the corner

A Fir, 40 ins. diam., bears N.58°E., 55 lks, dist. Old bearing tree, now dead. This tree appears to have been taken in the Wygant resurvey and not recorded.

A Fir, 10 ins. diam., bears N.84°E., 62 lks. dist.,

Marked T 27 S R 2 W S 36 S C B T; new B T

A Fir, 7 ins. diam., bears N.1°W., 67 lks. dist.,

Marked T 27 S R 2 W S 35 S C B T; new B T

The original bearing trees are all destroyed by fire
Land mountainous

Soil, eastern 15.00 chs. rocky; 3rd. & 4th. rate; balance clay loam; 2nd. & 3rd. rate

Timber, Fir, Hemlock, Pine and Cedar

Undergrowth, Vinemaple, rhododendron, Chinquapin, and Hemlock

N.89°26'W., retracing the S. bdy. of sec. 35

40.43 Fall, 95 lks. S. of the Angle Point; from which I run N.87°7'W.

41.05 Fall 67 lks. N. of angle Point

From the Standard cor. of secs. 35 & 36

N.88°5'W., resurveying the S. bdy. of sec. 35

Over Mountainous land, through old burn and dense undergrowth