

# County Surveyor's Record, Douglas County, Oregon

4967

East Boundary of Township 27 S., R. 4 W., W. M.  
as surveyed by Addison R. Flint, Deputy Surveyor,  
under Contract No. 56, dated March 1, 1855

CHAINS		
	North, on E. Bdy of sec. 36.	
	The correction on this line will be 147 lks. S. per mile.	
	Va.17*E.	
19.00	Brook, 4 lks. wide, runs, SE.	-40
22.47	Summit of ridge.	+75
32.47	Brook, 5 lks. wide, runs SE.	-30
40.00	Set $\frac{1}{4}$ sec. post, from which	+100
	A Cedar, 6 ins. dia., bears S.5*W., 8 lks. dis.	
	A Cedar, 6 ins. dia., bears N.4*E., 7 lks. dis.	
46.47	Summit of hill, E and W.	+50
78.00	Brook, 4 lks. wide, runs NW.	-200
79.50	Brook, 6 lks. wide, runs West.	-15
80.00	Set post cor. to secs. 30, 31, 25 and 36, from which	
	A Cedar, 24 ins. dia., bears S.40*E., 20 lks. dis.	
	A Cedar, 25 ins. dia., bears S.27*W., 30 lks. dis.	
	A Cedar, 4 ins. dia., bears N.15*W., 15 lks. dis.	
	A Fir, 4 ins. dia., bears N.38*E., 33 lks. dis.	
	Land, 3rd rate, very rough, hilly and broken.	
	Timber, principally, Fir and Cedar.	
	North, on E. Bdy. of sec. 25.	
	Va.18*30'E.	
40.00	Set $\frac{1}{4}$ sec. post, from which	+75
	A Laurel, 2 ins. dia., bears N.27*W., 20 lks. dis.	
	A Fir, 30 ins. dia., bears S.75*E., 10 lks. dis.	
80.00	Set post cor. to secs. 24, 25, 19 and 30, from which	+200
	A Fir, 15 ins. dia., bears N.27*E., 23 lks. dis.	
	A Fir, 14 ins. dia., bears S.76*E., 15 lks. dis.	
	A Fir, 15 ins. dia., bears S.78*W., 20 lks. dis.	
	A Fir, 8 ins. dia., bears N.67*W., 15 lks. dis.	
	Land, 3rd rate, rough hilly.	
	Timber, principally Fir and Cedar.	