

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 27 S., R. 3 W.

CHAINS

42.55 Creek, 3 lks. wide, course North East.

80.75 Intersect at cor. secs. <sup>5</sup>4, <sup>8</sup>5, 6 and 7.

Land, 3rd rate.

All timber and underbrush excepting the West Part of  
the mile. 2.75 chs.

Timber, Fir, Hemlock, Oak, Laurel, Maple and Ash.

## GENERAL DESCRIPTION of T. 27 S., R. 3 W., W. M.

The North tier of secs. in this Tp. is occupied by  
3 or 4 settlers, included in surveys. The land  
mountainous, mostly heavily timbered; Land, 2nd rate.  
Timber, Fir, Laurel, Cedar, Pine, Maple, Ash and dense  
underbrush.

South Boundary of Township 27 S., Range 3 W.,  
as surveyed by Sam C. Flint, Contract 454,  
dated June, 19, 1882.

I began at the standard corner of Tp. 27 S., R. 3 and 4 W.,  
which is a post, 4 ins. sq., mkd., S C T 27 S on N.,  
R 3 W <sup>S</sup> see 31 on E., R 4 W <sup>S</sup> see 36 on W. faces, with 6  
notches on N, E and W. faces, from which

A Laurel, 15 ins. dia., bears N.10°E., 21 lks. dist.  
mkd. S C T 27 S R 3 W S 31 B T.

A Laurel, 14 ins. dia., bears N.23°W., 18 lks. dist.  
mkd. T 27 S R 4 W S 36 B T.

A Laurel, 14 ins. dia., bears S.35°W., 22 lks. dist.  
mkd. T 28 S R 4 W S 1 B T.

A Laurel, 10 ins. dia., bears S.31°E., 17 lks. dist.

Thence I run <sup>≡</sup> on S. Bdy. of Sec. 31.

Va. 18°10'E.