

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 27 S., R. 3 W.

CHAINS

A Cedar, 30 ins. dia., bears S.85*W., 43 lks. dis.
mkd. $\frac{1}{4}$ S B T.

A Fir, 18 ins. dia., bears N.35*E., 80 lks. dis.
mkd. $\frac{1}{4}$ S B T.

80.00 Set Cedar post, 4 ft. long, 4 ins. sq., firmly in the ground
for cor. to secs. 23, 24 and 25 and 26, with 1
notch on E. and 2 notches on S. edges, from which

A Fir, 40 ins. dia., bears N.22*E., 115 lks. dis.
mkd. T 27 S R 3 W S 24 B T.

A Fir, 24 ins. dia., bears N.30*W., 53 lks. dis.
mkd. T 27 S R 3 W S 23 B T.

A Fir, 30 ins. dia., bears S.85*W., 43 lks. dis.
mkd. T 27 S R 3 W S 26 B T.

A Fir, 72 ins. dia., bears S.42*E., 68 lks. ^{dist.} ~~dia.~~
mkd. T 27 S R 3 W S 25 B T.

Land, 2nd and 3rd rate, mountainous, densely covered with
forests of Fir, Cedar, Hemlock and Laurel, with thick
undergrowth of Vine maple, Huckleberry and Balm.

East, on random line between secs. 24 and 25.

Va.19*E.

1.16 Spring branch, 2 lks. wide, course NW.

40.00 Set tem. $\frac{1}{4}$ Sec. cor.

70.00 Stream 10 lks. wide, course NW.

80.43 Intersect Tp. line, 66 lks. S. of cor. to secs. 24, 25,
19 and 30, which is a cedar post, firmly set in the
ground mkd. T 27 S R 2 W S 19 on NE., R 3 W S 24 on NW.,
S 25 on SW., and S 30 on SE. faces, with 2 notches on
S and 4 on N. edges, from which

A Fir, 28 ins. dia., bears N.15*E., 23 lks. dis.
mkd. T 27 S R 2 W S 19 B T.

A Laurel, 10 ins. dia., bears N.70*W., 34 lks. dis.
mkd. T 27 S R 3 W S 24 B T.