

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 27 S., R. 3 W.

CHAINS	
	<p>A Fir, 10 ins. dia., bears N.10*W., 18 lks. dis. mkd. $\frac{1}{4}$ S B T.</p> <p>A Fir, 6 ins. dia., bears S.30*E., 12 lks. dis. mkd. $\frac{1}{4}$ S B T.</p>
80.15	<p>Cor. to secs. 27, 28, 33 and 34. Land, 2nd rate. Densely covered with forests of Fir, Cedar, Hemlock and Laurel, thick undergrowth of Vine maple, Huckleberry, and Hazle. July 28, 1882</p>
40.00	<p style="text-align: right;">Va.18*45'E.</p> <p>North, on line bet. secs. 27 and 28.</p> <p>A Fir tree, 30 ins. dia., for $\frac{1}{2}$ sec. cor., mkd. on E. and W. faces, $\frac{1}{2}$ S., from which</p> <p>A Cedar, 6 ins. dia., bears S.15*E., 36 lks. dis. mkd. $\frac{1}{4}$ S B T.</p> <p>A Fir, 6 ins. dia., bears N.50*W., 20 lks. dis. mkd. $\frac{1}{4}$ S B T.</p>
45.50	<p>Creek, 3 lks. wide, course E. Commenced to ascend ridge.</p>
80.00	<p>Summit of ridge, NE., and SW. Set Laurel post, 4 ft. long, 4 ins. sq., firmly in the ground for cor. to secs. 21, 22, 27 and 28, mkd. T 27 S R 3 W S 22 on NE., S 21 on NW., S 28 on SW., and S 27 on SE., faces, with 2 notches on the S., and 3 on the E. edges, from which</p> <p>A Fir, 30 ins. dia., bears N.50*E., 52 lks. dis. mkd. T 27 S R 3 W S 22 B T.</p> <p>A Fir, 20 ins. dia., bears N.10*W., 37 lks. dis. mkd. T 27 S R 3 W S 21 B T.</p> <p>A Fir, 30 ins. dia., bears S.45*W., 6 lks. dis. mkd. T 27 S R 3 W S 28 B T.</p> <p>A Laurel, 15 ins. dia., bears S.50*E., 113 lks. dis. mkd. T 27 S R 3 W S 27 B T.</p> <p>Land, 3rd rate, densely covered with forests of Fir, Cedar, Laurel and Hemlock, with undergrowth of Vine maple, Huckleberry and Hazle.</p>