


County Surveyor's Record, Douglas County, Oregon

Resurvey of E. Bdy. of T. 27 S., R. 4 W.

CHAINS

- 48.00 Creek, 1 lk. wide, course NW., 110 ft. below $\frac{1}{4}$ sec. cor.
- 52.30 Draw, course NW.; ascend S. slope.
- 58.25 Trail, bears E. and W.
- 66.00 Ridge, bears NW and SE., 210 ft. above draw; thence along broken E. slope.
- 71.00 Spur, slopes E.; descend.
- 80.40 Apportioned distance.

Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the ground, for the cor. of secs. 7, 12, 13 and 18, with brass cap mkd.



from which

A Fir, 40 ins. diam., bears N.17*E., 17 lks. dist. mkd. T 27 S R 3 W S 7 B T.

A Fir, 8 ins. diam., bears S.16*45'E., 61 lks. dist. mkd. T 27 S R 3 W S 18 B T.

A Fir, 30 ins. diam., bears S.58*W., 43 lks. dist. mkd. T 27 S R 4 W S 13 B T.

A Fir, 12 ins. diam., bears N.54*W., 46 lks. dist. mkd. T 27 S R 4 W S 12 B T.

This cor. is on a spur sloping NE.

Land, mountainous.

Soil, light, gravelly loam; 3rd rate.

Timber, Fir, Cedar, Hemlock and Laurel.

Undergrowth, Maple, second-growth, Laurel and Salal-berry.