

Remeasurement of Sixth Standard Parallel (South Bdy. T. 27 S., R. 4 W.) Addison R. Flint, Deputy Surveyor Under Contract No. 56, dated March 1, 1855

| | | |
|---------------|---|--|
| <p>CHAINS</p> | <p>I run West on random line setting temporary half mile and mile posts at 40.00 and 80.00 chs. and intersected West boundary of T. 27 S., R. 4 W., at 6 miles, 1 ch. and 35 lks. and 147 lks. North of SW. cor. to T. 27 S., R. 4 W.</p> <p>The Sixth Standard Parallel having been since examined and admitted to be in error by the Deputy who surveyed it, I run, according to instructions from the Surveyor General, due East establishing closing corners on the Stan. Parallel as shows in notes of subdivisions T. 27 S., R. 4 W.</p> <p>East, on 6th Standard Parallel (Corrected line) Va. 18°E.</p> <p>41.35 Set 1/4 sec. post, from which A W oak, 5 ins. diam., bears S.35°W., 24 lks. dist. A W oak, 6 ins. diam., bears N.68°E., 59 lks. dist.</p> <p>81.35 Set post cor. to secs. 31 & 32, from which A fir, 3 ins. diam., bears N.32°W., 16 lks. dist. A fir, 3 ins. diam., bears S.11°W., 22 lks. dist. A dogwood, 4 ins. diam., bears N.43°E., 26 lks. dist. A cedar, 4 ins. diam., bears S.28°E., 17 lks. dist.</p> <p>Land, 3rd rate Timber, fir, oak, cedar & laurel</p> | |
| | <p>East, on South bdy. of sec. 32 Va. 18°15'E.</p> <p>12.00 Summit of ridge +75</p> <p>24.00 Brook, 4 lks. wide, runs SW. -65</p> <p>40.00 Set 1/4 sec. post, from which +30 A fir, 8 ins. diam., bears S.33°E., 25 lks. dist. A fir, 10 ins. diam., bears N.25°E., 13 lks. dist.</p> <p>50.00 Summit of ridge +25</p> <p>80.00 Set post cor. to secs. 32 & 33, from which -80</p> | |