

41

Exteriors of T. 28 S., R. 4 W.
 as Surveyed by W. H. Byars, Deputy Surveyor
 Under Contract No. 376
 Dated January 22, 1881

CHAINS	
	Begin at the post established for the corner to Townships 27 and 28 South, Ranges 4 & 5 West. Post and one witness tree standing, viz: A W oak, 16 ins. diam., bears N.14 $\frac{1}{2}$ *W., 480 lks. dist. East, on line on N. boundary of section 6. Retrace old line Va. 18*30'E.
4.36	Enter creek, 50 lks. wide, course S.89*W.
10.00	Leave creek
10.50	Road
12.00	Enter timber
15.00	Begin ascent
35.00	Top of ridge, course NE.
40.35	Intersect $\frac{1}{4}$ sec. cor. and set new post as per instructions, from which A W oak, 5 ins. diam., bears S.35*W., 24 lks. dist. A W oak, 6 ins. diam., bears N.68*E., 59 lks. dist.
68.85	Stream, 40 lks. wide, course NW.
73.85	Road course NW.
80.28	Section cor. to secs. 5, 6, 31 & 32 cor. & bearing ^{Trees} all standing viz: A fir, 3 ins. diam., bears N.32*W., 16 lks. dist. A fir, 3 ins. diam., bears S.11*W., 22 lks. dist. A dogwood, 4 ins. diam., bears N.43*E., 26 lks. dist. A cedar, 4 ins. diam., bears S.28*E., 17 lks. dist.
	Land, chiefly mountainous, 3rd rate Heavily timbered, principally fir, cedar & hemlock East, on North boundary of Section 5 Va. 18*30'E.
17.30	Fence course N.
24.40	Creek course SW., 2 lks. wide
40.00	Qr. sec. cor., bearing trees standing Set new cor. post, as per instructions, viz: A fir, tree, 8 ins. diam., bears S.33*E., 25 lks. dist.