

Exteriors of T. 28 S., R. 4 W.

CHAINS

79.95

Sec. cor. Set new post witness trees all standing, viz:

A laurel, 14 ins. diam., bears N.40*E., 21 lks. dist.

A laurel, 10 ins. diam., bears S.31*E., 17 lks. dist.

A laurel, 14 ins. diam., bears S.35*W., 22 lks. dist.

A laurel, 14 ins. diam., bears N.23*W., 18 lks. dist.

March 10, 1881

Land, chiefly mountainous, 3rd rate

Heavily timbered, principally fir, cedar & hemlock

Resurvey and Retracement of Subdivisions, T. 27 S., R. 4 W.
As surveyed by Elmer F. Strickler, Deputy Surveyor
Under Special Instructions, Dated Jan. 22, 1917

I commence at the cor. of secs. 25, 26, 35 & 36, T. 27
S., R. 4 W., and I run

East, retracing the line bet. secs. 25 & 36; at 39.80
chs., after careful and diligent search, am unable to
find any trace of the old $\frac{1}{4}$ sec. cor., set temp. cor.,
and at 76.91 chs. fall 119 lks. N. of the cor. of secs.
25, 30, 31 and 36 on the E. bdy. of the Tp., previously
described.

Thence

N.89*07'W., resurveying the line bet. secs. 25 and 36

Descend W. slope through heavy timber and dense under-
growth

.90 Creek, 5 lks. wide, course NW., 45 ft. below sec. cor.

Along a broken N. slope

15.00 Spur, 80 ft. above creek, slopes NW.; descend W. slope

19.00 Creek, 1 lk. wide, course NW., 80 ft. below spur.

28.40 Creek, 1 lk. wide, course NW., 180 ft. below spur

36.92 Set a yew post, 3 ft. long, 4 ins. sq., 24 ins. in the
ground, for $\frac{1}{4}$ cor. of sec. 25 only, marked $\frac{1}{4}$ S 85 on
N. face; from which

A yew, 5 ins. diam., bears N.67*W., 17 lks. dist.

Marked $\frac{1}{4}$ S 25 B T

A fir, 24 ins. diam., bears N.38*E., 47 lks. dist.

Marked $\frac{1}{4}$ S 25 B T