

## County Surveyor's Record, Douglas County, Oregon

59

Meanders of South Fork of Umpqua River,  
T. 27 S., R. 6 W.

## CHAINS

N.9 $\frac{1}{2}$ *E.	7.80	
N.31 $\frac{1}{2}$ *W.	7.60	
N.17*W.	3.50	Along foot of steep rocky bluff.
N.4 $\frac{1}{2}$ *W.	14.50	To Meander post bet. Secs. 24 & 25.
N.10*W.	26.80	In Section 24.
N.15 $\frac{1}{4}$ *W.	9.10	
N.1*E.	2.60	
N.14*E.	3.40	
N.23*E.	6.40	
N.43 $\frac{1}{2}$ *E.	10.40	Bank brushy.
N.65*E.	6.60	
N.74 $\frac{1}{2}$ *E.	5.80	
N.61 $\frac{1}{2}$ *E.	9.90	
N.64*E.	4.90	Bank, 12 ft. high
N.70*E.	4.70	To Meander post in E. bdy. of Tp.
N.58*W.	9.30	In Section 13.
N.85*W.	3.50	
N.60*W.	7.00	
N.79 $\frac{1}{2}$ *W.	19.00	At 3.90 enter Huntley's field. At 9 chs. N.65*E. 3 chs. to house. Leave field, N. and S.
N.87 $\frac{3}{4}$ *W.	16.00	At 12.35 chs. a stream 12 lks.wide, nearly dry, from North.
S.59*W.	5.00	Along foot of steep bluff.
S.80 $\frac{1}{4}$ *W.	2.00	
S.79 $\frac{1}{2}$ *W.	11.00	In Section 13.(Enter Stanley's field N. and S.)
S.89 $\frac{1}{2}$ *W.	2.50	
S.68 $\frac{1}{2}$ *W.	9.50	To meander post bet. Secs. 13 & 14.
N.87*W.	1.70	In Section 14.
S.70 $\frac{1}{2}$ *W.	12.00	At 5 chs. Stanley's house bears N. 2 chs., at 6.10 chs. leave field, N. and S.