

Meanders of South Fork of Umpqua River,
T. 27 S., R. 6 W.

CHAINS		
S.86*E.	7.00	
S.80 $\frac{3}{4}$ *E.	6.50	Along foot of steep rocky bluff.
S.42 $\frac{1}{2}$ *E.	7.50	
N.87 $\frac{1}{8}$ *E.	2.70	To meander post bet. Secs. 34 & 35.
<hr/>		
S.44 $\frac{1}{2}$ *E.	8.20	In Section 35.
S.52 $\frac{1}{4}$ *E.	4.20	Bank, low and brushy.
S.46 $\frac{3}{4}$ *E.	7.80	To meander post in S. bdy. of Tp.
<hr/>		
N.29 $\frac{1}{2}$ *E.	5.30	In Section 36. (Beginning at post in S. bdy.)
N.34 $\frac{3}{4}$ *E.	11.50	Bank, about 10 ft. high.
N.18 $\frac{1}{4}$ *E.	7.70	Very brushy. Soil, sandy.
N.15*E.	5.00	
N.11*E.	4.50	
N.15*W.	7.60	
N.22*W.	3.40	Timber, Ash, Alder, Balm, etc.
N.71 $\frac{1}{4}$ *W.	6.10	
S.89*W.	10.90	To meander post bet. Secs. 35 & 36.
<hr/>		
S.75*W.	4.40	In Section 35.
S.84*W.	5.70	Bank, low and brushy.
N.71*W.	4.30	
N.79*W.	2.90	Along foot of steep bluff.
N.37 $\frac{1}{2}$ *W.	11.10	Current, rapid.
N. $\frac{3}{4}$ *W.	5.20	Bank, rocky.
N.20*W.	7.00	
N.8 $\frac{1}{2}$ *E.	5.10	
N.25 $\frac{1}{2}$ *E.	6.00	Bank, low and very brushy.
N.26 $\frac{3}{4}$ *E.	6.90	To meander post bet. Secs. 26 & 35.
<hr/>		
N.24 $\frac{1}{4}$ *E.	4.80	In Section 26.