

## County Surveyor's Record, Douglas County, Oregon

66

Meanders of South Fork of Umpqua River,  
T. 27 S., R. 6 W.

## CHAINS

N.18 $\frac{1}{2}$ *E.	11.50	
N.15 $\frac{1}{2}$ *E.	11.50	
N.25 $\frac{1}{2}$ *E.	6.00	
N.26 $\frac{1}{2}$ *E.	6.60	
N.37 $\frac{1}{2}$ *E.	7.20	To meander post bet. Secs. 9 & 16.

N.13 $\frac{1}{2}$ *E.	24.90	In Section 9.
N.15 $\frac{1}{2}$ *E.	2.20	
N.10 $\frac{1}{2}$ *W.	2.80	
N.44*W.	11.70	
N.2 $\frac{1}{2}$ *W.	9.00	
N.9 $\frac{1}{2}$ *W.	14.70	
N.8*W.	7.80	
N.18*W.	7.60	
N.5 $\frac{3}{4}$ *W.	4.30	To meander post bet. Secs. 4 & 9

N.7 $\frac{1}{2}$ *E.	7.90	In Section 4.
N.12 $\frac{1}{2}$ *W.	12.50	
N.21 $\frac{1}{4}$ *W.	15.80	
N.23*W.	32.75	
N.30*W.	9.10	
N.40*W.	11.40	To meander post in N. bdy. of Tp.

S.51 $\frac{1}{2}$ *W.	10.40	In Section 5.
S.61*W.	11.45	Bank about 15 ft. high and brushy.
S.40*W.	12.75	
S.32 $\frac{1}{2}$ *W.	17.50	
S.30 $\frac{1}{2}$ *W.	8.60	
S.9*W.	7.00	
S.11 $\frac{1}{2}$ *W.	18.85	
N.78 $\frac{1}{4}$ *W.	19.00	Steep bank, 50 ft. high.
N.72 $\frac{3}{4}$ *W.	9.00	Bank, low and brushy.
N.46*W.	4.50	To meander post bet. Secs. 5 & 6.