

Subdivisions of T. 27 S. R. 7 W.

CHAINS	<p>A Fir, 15 ins. diam., bears N.15*E., 12 lks. dist.</p> <p>A Laurel, 12 ins. diam., bears S.10*W., 30 lks. dist.</p>
80.41	<p>The cor. to Secs. 19, 20, 29 and 30.</p> <p>The Eastern slope of the Coast Range Mountains is exceedingly precipitous and difficult of passage, up or down. The land on this mile is third or fourth rate. Timber, Fir, Hemlock, Cedar, Spruce, Yew, Maple and Laurel. Brush, thick and troublesome to get through.</p>
	<p>West, on random, between Secs. 18 and 19.</p> <p>The post at cor. to Secs. 17, 18, 19 and 20 not found. Made and set new post and found all the old witness trees, viz:</p> <p style="padding-left: 40px;">Oak, 24 ins. diam., bears S.72*W., 77 lks. dist.</p> <p style="padding-left: 40px;">Oak, 24 ins. diam., bears S.65*E., 112 lks. dist.</p> <p style="padding-left: 40px;">Oak, 18 ins. diam., bears N.22*W., 270 lks. dist.</p> <p style="padding-left: 40px;">Oak, 10 ins. diam., bears S.82*E., 400 lks. dist.</p> <p style="text-align: right; padding-right: 40px;">Va.19*15'E.</p>
40.00	Set temporary $\frac{1}{4}$ Sec. Cor.
41.50	Summit of Coast Range Mountains.
79.64	<p>Intersected West bdy. of Tp. at 47 lks. South of the cor. to Secs. 18, 19, 13 and 24.</p> <p>Thence, I ran S.89*40'E. on true line, between Secs. 18 and 19, with same Va.</p>
39.64	<p>Set Laurel <math>\frac{1}{4}</math> post, 3 ins. diam., 3 ft. long, firmly in the ground, from which</p> <p style="padding-left: 40px;">A Fir, 30 ins. diam., bears N.45*E., 55 lks. dist.</p> <p style="padding-left: 40px;">A Fir, 24 ins. diam., bears N.60*E., 65 lks. dist.</p>
79.64	<p>The cor. to Secs. 17, 18, 19 and 20.</p> <p>Land, third rate.</p> <p>Timber, Fir, Hemlock, Cedar, Maple and Alder.</p> <p>Brush, bad.</p>