

Subdivisions of T. 27 S., R. 7 W.

CHAINS

North, between Secs. 17. and 18.

Va.19*15'E.

3.00 Began to ascend mountain.

32.50 Rocky bluffs, continuous for last 30 chs..

40.00 Set a post, 3 ft. long, 3 ins. sqr., firmly in the ground for $\frac{1}{4}$ Sec. cor., from which

A Laurel, 6 ins. diam., bears N.15*E., 16 lks. dist.

A Fir, 8 ins. diam., bears S.85*E., 32 lks. dist.

At 40.00 chs., offset West 5.50 chs., which brings us to summit of mountain; thence North 10.00 chs.; thence East.

50.00 5.50 to line; thence along West.

80.00 of ridge to cor. Set a post, 3 $\frac{1}{2}$ ft. long and 4 ins. sqr. firmly in the ground for cor. to Secs. 7, 8, 17 and 18, from which

A Fir, 15 ins. diam., bears N.40*E., 24 lks. dist.

A Fir, 8 ins. diam., bears S.75*E., 27 lks. dist.

A Fir, 14 ins. diam., bears N.62*W., 31 lks. dist.

A Fir, 40 ins. diam., bears S.70*W., 25 lks. dist.

Land, third rate; very broken, rocky cliffs and difficult to get over.

Timber, Fir, Cedar, Hemlock, Chinquapin, Laurel and Maple.

Brush, bad as usual.

July 13, 1881.

East on random line, between Secs. 8 and 17.

va.19*15'E.

31.60 Summit of mountain ridge- at 31.60 we made an offset, North 3.50 chs. to avoid a steep precipice; thence,

45.10 East 13.50 chs.; thence, South 3.50 chs. to line; thence, to avoid another cliff of rocks, I ran N.45*E. 4.00 chs.;