

## Subdivisions of T. 27 S., R. 7 W.

CHAINS

Land, third rate.

The Cedar and Fir timber on the first half of this mile is unusually good; the balance of the mile, Fir, Cedar, Hemlock and the usual forest trees.

Brush, on the first half mile is not bad; last half quite plenty.

July 14, 1881.

North, between Secs. 7 and 8.

Va.19\*15'E.

- 10.30 Stream, 4 lks. wide, course West.
- 19.75 Stream, 3 lks. wide, course S.65\*W.
- 40.00 Set post, 3 ft.long, 4 ins. sq. for  $\frac{1}{4}$  Sec. cor., from which,
- A Fir, 6 ins. diam., bears N.20\*E., 11 lks. dist.
- A Cedar, 10 ins. diam., bears S.30\*W., 20 lks. dist.
- 42.50 Stream, 2 lks. wide, course S.30\*W.
- 48.00 Stream, 2 lks. wide, course South.
- 80.00 Cor. to Secs. 5, 6, 7 and 8. Set a Laurel post  $3\frac{1}{2}$  ft. long, 4 ins. sq. firmly in the ground, from which,
- A Fir, 36 ins. diam., bears N.75\*W., 6 lks. dist.
- A Fir, 30 ins. diam., bears N.50\*E., 57 lks. dist.
- A Fir, 36 ins. diam., bears S.80\*E., 75 lks. dist.
- A Fir, 36 ins. diam., bears S.30\*W., 40 lks. dist.
- The land on this mile is broken, about third rate, the streams rapid, the ridges steep and precipitous.
- Timber, Fir, Cedar, Hemlock, Spruce, Laurel, Maple and Alder.

East, on random line, between Secs. 5 and 8.

Va.19\*15'E.

- 25.00 Summit of Coast Range mountain.