

Subdivisions of T. 27 S., R. 7 W.

CHAINS

A Fir, 36 ins. diam., bears North, 6 lks. dist.

A Fir, 30 ins. diam., bears S.20*W., 33 lks. dist.

79.10 Cor. to Secs. 5, 6, 7 and 8.

Land, third rate. Broken, cut up by streams and sharp ridges.

Timber, Fir, Cedar, Hemlock, Maple, Alder and Laurel.

Brush, thick and plenty.

North, on random, between Secs. 5 and 6.

Va. 19*15'E.

40.00 Set temporary $\frac{1}{4}$ Sec. cor.

The above $\frac{1}{4}$ mile is mostly open timber, free from underbrush - worth special notice.

58.15 Summit of Mt. Callahan.

66.00 Perpendicular cliff of rocks.

78.30 Intersected North boundary of Tp., 65 lks. West, from cor. to Secs. 5, 6, 31 and 32. Thence, we ran, S.0*28'W. on true line, between Secs. 5 and 6, with same Va.

38.30 Set post, 3 ft. long, 4 ins. sq. for $\frac{1}{4}$ Sec. cor., from which,

A Fir, 8 ins. diam., bears N.55*W., 12 lks. dist.

A Fir, 6 ins. diam., bears N.75*E., 25 lks. dist.

78.30 Cor. to Secs. 6, 5, 8 and 7.

Land, on first $\frac{1}{2}$ of above mile is used as a cattle range; the last $\frac{1}{2}$ is very broken and rough.

Timber, Fir, Cedar, Yew, Hemlock, Laurel, Maple and Alder.

July 16, 1881.