

Retracement of the 6th Standard Parallel South, through R. 8 W.

CHAINS

General Description.

The 6th Standard Parallel South, for the first three miles through Range 8 West is over very rough land, terminating in a very abrupt descent to Wilson's Creek.

The last three miles are through good fir, cedar and other varieties of timber.

No stone of value was observed along the line.

The land along the last two miles would make good farms if cleared.

The country is well watered from Wilson Creek, West.

The old markings along this line are plain except from the summit of the Coast Range Mountains, East to the Northwest cor. of Sec. 1.

William P. Heydon.
U.S. Deputy Surveyor.

Corrections in the Survey of the 6th. Std. Parallel South through R. 8 W.

Same Deputy and Contract.

Survey commenced.

I begin at the Std. Cor. for T 27 S Rs. 7 and 8 W. which is a post marked as described by the Examiner, to wit: T 27 S R 8 W S 36 on W, S C T 27 S R 8 W on N, T 27 S R 7 W. on E. faces, with 6 grooves on E. and W. faces. Witness trees correspond in bearing and distance with original notes. I erase redundant markings on post and mark with 6 grooves on N. face to correspond with the notes thereof on file in the U.S. Surveyor General's Office. viz: S C T 27 S on N, R 7 W S 31 on E, R 8 W S 36 on W. faces, with 6 grooves on NE. and W. faces; Thence I run

West on S. bdy. of Sec. 36, tracing without remeasuring.

Find the $\frac{1}{4}$ sec. cor. marked as reported by Examiner, and the white oak witness tree to bear N.53*E., 60 lks. dist. instead of N.73*E., 6 lks dist. as reported