

Corrections in the Survey of the 6th Std.  
Parallel South through R. 8 W.

CHAINS

in original notes. I erase redundant markings on the post to conform with original notes.

Find the Standard Cor. to Secs. 35 and 36, a post marked and witnessed as reported by the Examiner, namely:

S C T 27 S R 8 W on N, S C T 27 S R 8 W S 36 on E, T 27 S on S, S C T 27 S R 8 W S 35 on W. faces, with 1 groove on E. and 5 grooves on W. faces, from which A laurel, 16 ins. diam., bears N.80°E., 16 lks. dist., marked T 27 S R 8 W S 36 B T.

A laurel, 8 ins. diam., bears N.60°W., 25 lks. dist., marked T 27 S R 8 W S 35 B T.

I erase redundant markings on the post, and also the S C on the witness tree.

Thence I continue West along this Standard Parallel to the Standard corner of T 27 S Rs. 8 and 9 W. and examine each Standard  $\frac{1}{2}$  Sec. and Sec. Cor. thereon, verify the witnesses thereto and where necessary, correct the markings to conform to the notes thereof on file in the U. S. Surveyor General's Office.

William P. Heydon.  
U.S. Deputy Surveyor.

Corrections in the Survey of the Exterior's  
of T.27 S., R. 8 W.  
Same Deputy and Contract.

From the Standard Corner of T 27 S Rs. 8 and 9 W.

I run

North, along the West bdy. of T 27 South, R 8 W. tracing without remeasuring and examine each cor. established by me thereon. Wherever necessary I corrected markings to conform with the notes thereof on file in the U.S. Surveyor General's Office. I also verified the witnesses to each cor.

William P. Heydon.  
U.S. Deputy Surveyor.