

West Edy. of T. 27 S., R. 8 W., M.

CHAINS

51.75 Fir, 60 ins. diam. on line. I mark with 2 notches on N. and S. sides.

64.75 A fir, 40 ins. diam. on line, I mark with 2 notches on N. and S sides.

74.00 Foot of descent, 600 ft. below $\frac{1}{2}$ sec. cor.

80.00 Set a myrtle post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for cor. of secs. 1, 6, 7, and 12, marked T 27 S S 6 on NE., R 8 W S 7 on SE., S 12 on SW., and R 9 W S 1 on NW. faces, with 5 notches on S. and 1 notch on N. edges, from which

A madrone, 16 ins. diam., bears N.83°E., 110 lks. dist., marked T 27 S R 8 W S 6 B T.

A fir, 40 ins. diam., bears S.5°30'E., 20 lks. dist., marked T 27 S R 8 W S 7 B T.

A fir, 7 ins. diam., bears S.15°15'W., 45 lks. dist., marked T 27 S R 9 W S 12 B T.

A fir, 18 ins. diam., bears N.70°W., 50 lks. dist., marked T 27 S R 9 W S 1 B T.

Land, mountainous.

Soil, 2nd rate to $\frac{1}{2}$ sec. cor. last 40 chs. 4th rate.

Timber, fir and hemlock, dead and mostly fallen.

Undergrowth, laurel willow, hemlock, arrow-wood and fir.

Mountainous land, or land covered with dense undergrowth, 80.00 chs.

July 28, 1896.

July 29, 1896.

North bet. secs. 1 and 6.

Ascend from cor.

4.00 Top of sharp spur, 100 ft. above cor. Descend rapidly.

20.00 Coos River, 100 lks. wide, course W. 300 ft. below summit of spur, and ascend steep mountain side through good timber and dense brush.

40.00 Set a fir post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for $\frac{1}{2}$ sec. cor. marked $\frac{1}{2}$ S. on W. face, from which