

West Bdy. of T. 27 S., R. 8 W. W. M.

CHAINS

To learn the condition of the S. bdy. of T. 25 S R 8 W.
I run from the cor. last above described. East along S.
bdy. of Sec. 31.

12.50 A creek, 4 lks. wide, course SE.

15.25 A creek, 15 lks. wide, course South.

17.00 A fir, 13 ft. and 7 ins. diam.

40.05 $\frac{1}{4}$ sec. cor. witness trees still standing.

75.00 Stream, 2 lks. wide, course S.

80.12 Cor. to secs. 5, 6, 31 and 32.

Witness trees all standing. I therefore conclude this
line runs E. and W.

General Description.

This line passes over very fair land and through excell-
ent timber, except the last two miles, which is very
rough and mountainous, covered with fallen timber,
brush and briars.

Total length of line over mountainous land or through
dense undergrowth, 480.08 chains.

William P. Heydon.
U.S. Deputy Surveyor.

Subdivisions T. 27 S., R. 8 W.
Same Deputy and Contract.

Aug. 2, 1896.

From the established Standard South East cor. of sec. 36
T 27 S R 8 W. with the foregoing named assistants, I
run N. on a trial line to retrace the E. bdy. of sec.
36.

Va.20*07'E.

7.38 Dry gulch, course E. 60 ft. above cor.

11.75 Branch, 2 lks. wide, flows SE.

40.00 $\frac{1}{4}$ sec. cor. bet. secs. 31 and 36, 4 lks. W. Still ascend.

60.00 Enter fir timber at spur of Mountain on left, 250 ft.
above branch; descend.