

## Subdivisions of T. 27 S., R. 8 W.

| CHAINS |   |
|--------|---|
| 79.98  | Intersect North and South line, 14 lks. North of cor. to secs. 3, 4, 9 and 10.  |
|        | Thence I run  |
|        | N.89°51'W. on a true line bet. secs. 4 and 9.   |
|        | Descend from cor. through old burn.   |
| 12.48  | A fir, 48 ins. diam., on line, I mark with 2 notches on East and West sides.  |
| 39.99  | Set a yew post, 3 ft. long, 4 ins. sq. 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S. on N. face, from which   |
|        | A hemlock, 24 ins. diam., bears N.40 $\frac{1}{2}$ °W., 27 lks. dist. Marked $\frac{1}{4}$ S B T  |
|        | A hemlock, 16 ins. diam., bears S.44°W., 32 lks. dist. Marked $\frac{1}{4}$ S B T   |
| 55.25  | Spring branch 3 lks. wide, course NW. 175 ft. below sec. cor. and ascend  |
| 70.00  | Branch 2 lks. wide, course NW.  |
| 75.00  | Summit of spur, 150 ft. above branch, and descend steep slope. Bearing of spur NW.  |
| 79.98  | The cor. of secs. 4, 5, 8 and 9.  |
|        | Land, mountainous   |
|        | Soil, 3rd rate  |
|        | Timber, fir, hemlock and cedar, nearly all dead and fallen  |
|        | Undergrowth, fir, hemlock, maple and willow   |
|        | Mountainous land or land covered with dense undergrowth,  |
|        | 79.98 chs. <span style="float: right;">Aug. 28, 1896.</span>  |
|        | N.0°3'W. on a random line bet. secs. 4 and 5.   |
| 40.00  | Set temp. $\frac{1}{4}$ sec. cor.   |
| 80.00  | Could find no trace of old cor. to secs. 4, 5, 32 and 33 on North bdy. of the Tp. it having been destroyed by fire. I go now to the cor. of secs. 3, 4, 33 and 34, which is a post, 12 ins. above ground marked and witnessed as described by the surveyor general. |