

Subdivisions of T. 27 S., R. 8 W.

CHAINS	
74.40	Offset E. 75 lks. to avoid rocky bank of river
79.90	Offset back to line
80.00	Set fir post, 3 ft. long, 4 ins. sq. 24 ins. in the ground
	for cor. of secs. 5, 6, 7 and 8, 150 ft. above river,
	marked T 27 S S 5 on NE, R 8 W S 8 on SE, S 7 on SW and
	S 6 on NW faces, with 5 notches on S. and E. edges, from
	which
	A laurel, 14 ins. diam., bears N.52°E., 75 lks.
	dist. Marked T 27 S R 8 W S 5 B T
	A fir, 16 ins. diam., bears S.80°E., 43 lks. dist.
	Marked T 27 S R 8 W S 8 B T
	A hemlock, 20 ins. diam., bears S.65°10'W., 24 lks.
	dist. Marked T 27 S R 8 W S 7 B T
	A cedar, 12 ins. diam., bears N.32°30'W., 122 lks.
	dist. Marked T 27 S R 8 W S 6 B T
	Land, mountainous
	Soil, 4th rate
	Timber, fir, hemlock and cedar, with some myrtle along
	Coos River
	Undergrowth, laurel, willow and vine maple
	Mountainous land or land covered with dense undergrowth,
	80.00 chs.
	Sept. 8, 1896.
	N.89°43'E., on a random line bet. secs. 5 and 8
40.00	Set temp. $\frac{1}{4}$ sec. cor.
80.20	Intersect N. and S. line 24 lks. N. of cor. of secs. 4, 5,
	8 and 9
	Thence I run
	S.89°53'W., on a true line bet. secs. 5 and 8
2.50	Small branch, 2 lks. wide, course NW. Ascend
7.50	Spur, 100 ft. above stream. Descend. Spur slopes N.
20.00	Panther Creek, 25 lks. wide, course SW. 250 ft. below
	spur. This crossing is 5.00 chs. above creek junction
	with Coos River.