

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 28 S., R. 1 W.

## CHAINS

A fir, 24 ins. diam., bears S.25\*W., 63 lks. dist.,  
marked T 28 S R 1 W S 23 B T.

A fir, 24 ins. diam., bears N.85\*W., 67 lks. dist.,  
marked T 28 S R 1 W S 14 B T.

Land, mountainous.

Soil, 4th. rate.

Timber, fir, hemlock, pine, and cedar.

Undergrowth, laurel and vine maple.

Mountainous or heavily timbered land or land covered with  
dense undergrowth. 80.00 chs.

S.89\*56'E. on a random line bet. secs. 13 and 24.

40.00 Set temp  $\frac{1}{4}$  sec. cor.

79.86 Intersect will Mer. 5 lks. N. of the cor of sec. 13 and  
24, which I established, June 28, 1902.

Thence I run.

N.89\*54'N. on a true line, bet. secs. 13 and 24.

Descend through heavy timber, and dense undergrowth.

5.25 A creek, 15 lks. wide, course, SE.

15.00 A spring branch, 2 lks. wide, course NE.

39.92 Set a basalt stone, 15x6x6 ins., 10 ins. in ground for  
 $\frac{1}{4}$  sec. cor., marked  $\frac{1}{4}$  on N. face; from which,

A cedar, 30 ins. diam., bears N.25\*E., 28 lks. dist.,  
marked  $\frac{1}{4}$  S 13 B T.

A fir, 30 ins. diam., bears S.5\*W., 26 lks. dist.,  
marked  $\frac{1}{4}$  S 24 B T.

79.86 The cor. of secs. 13, 14, 23 and 24.

Land, mountainous.

Soil, 4th rate.

Timber, fir, hemlock, cedar, pine and laurel.

Mountainous or heavily timbered land or land covered  
with dense undergrowth. 79.86 chs.

N.0\*1'W. bet. sec. 13 and 14.

Ascend through heavy timber and dense undergrowth.