

23

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 28 S., R. 1 W.

CHAINS

Thence I run.

N.89*44'W. on a true line bet. secs. 12 and 13.

Ascend through heavy timber and dense undergrowth, bears SE. and NW.

15.75 Top of divide, 1000 ft. high, bears SE. and NW.

Descend.

~~29.92~~ Set a basalt stone, 15x12x8 ins., 10 ins. in ground for**39.92** $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N. face; from which,A fir, 12 ins. diam., bears N.31*E., 130 lks. dist., marked $\frac{1}{4}$ S 12 B T.A fir, 16 ins. diam., bears S.36*E., 50 lks. dist., marked $\frac{1}{4}$ S 13 B T.

63.00 Top of divide, course N. and S.

Descend.

68.50 Dry run, course N. thence along side of mountain, bears N. and S.

79.84 The cor. of secs. 11, 12, 13 and 14.

Land, mountainous.

Soil, stony and 4th. rate.

Timber, fir, hemlock, laurel, pine and cedar.

Undergrowth, laurel and vine maple.

Mountainous, or heavily timbered land or land covered with dense undergrowth. 79.84 chs.

August 12, 1902

At the cor. of secs. 11, 12, 13, and 14

Thence I run.

N.0*1'W., bet. secs. 11 and 12.

Descend through heavy timber and dense undergrowth, bears E. and W.

8.75 A spring branch, 2 lks. wide, course W.

Ascend.

13.25 Top of spur, course E. and W.

Descend.

18.40 Foot of descent.

Dry run, course, NW.

CORRECTED 3/17/2010
JC DCSO