

County Surveyor's Record, Douglas County, Oregon

West Boundary of T. 28 S., R. 2 W.

CHAINS

dense underbrush and heavy timber.

Descend NE slope.

- 4.00 Creek, 4 lks. wide, flows SE.; ascend S slope.
- 16.00 Top of ridge, bears SW and NE.; descend SW slope.
- 40.00 Set granite stone, 8x12x14 ins., 10 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on W face, from which
- A fir, 48 ins. diam., bears S.41*E., 40 lks. dist., marked $\frac{1}{4}$ S 30 B T.
- A fir, 30 ins. diam., bears N.82*W., 47 lks. dist., marked $\frac{1}{4}$ S 25 B T.
- 44.00 Ascend S slope.
- 54.00 Tuttle trail, bears NW and SE.
- 58.00 Top of ridge, bears E and W.; descend N slope.
- 68.50 Creek, 6 lks. wide, flows NE.; ascend S slope.
- 80.00 Set lava stone, 6x12x16 ins., 11 ins. in the ground for cor. secs. 19, 24, 25 and 30, marked with 4 notches on N and 2 notches on S edge, from which
- A hemlock, 26 ins. diam., bears N.29*E., 52 lks. dist., marked T 28 S R 2 W S 19 B T.
- A fir, 30 ins. diam., bears S.60*E., 24 lks. dist., marked T 28 S R 2 W S 30 B T.
- A fir, 30 ins. diam., bears S.25*W., 47 lks. dist., marked T 28 S R 3 W S 25 B T.
- A hemlock, 30 ins. diam., bears N.48*W., 24 lks. dist., marked T 28 S R 3 W S 24 B T.
- Land, mountainous.
- Soil, rocky; 4th rate.
- Timber, fir, cedar and hemlock..
- Underbrush, young firs, rhododendrons, vine maple and greasewood.
- Land mountainous, covered with dense underbrush or heavily timbered and exceptionally difficult to survey, 80.00 chs.

September 4, 1909.