

County Surveyor's Record, Douglas County, Oregon

South Boundary of T. 28 S., R. 2 W.

CHAINS

Land, mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey, 80.00 chs.

September 7, 1909.

GENERAL DESCRIPTION.

This fractional township is rough and mountainous, and contains very little agricultural land. There is a good stand of timber in most parts. This is chiefly fir, cedar, yellow pine and hemlock.

Subdivision of T. 28 S., R 2 W.
As surveyed by Wm. N. Gibb, deputy surveyor
Under contract No. 783, dated Dec. 3, 1908.

Thence I run

N.3'E., on true line, bet. secs. 34 and 35, through underbrush and scattering timber; descend NE slope.

3.40 Ravine, bears NE.; ascend SE slope.

16.00 Ridge, bears E and W.; descend NE slope.

28.10 Ravine, bears E.; ascend steep S slope.

40.00 Set lava stone, 6x7x15 ins., 10 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on W face, and raise mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, W of cor., from which

A chinquapin, 7 ins. diam., bears N.42*W., 17 lks. dist., marked $\frac{1}{4}$ S 34 B T.

Cor. is on top of ridge, bearing E and W.; descend NE slope.

52.00 Ravine, bears E.; ascend S slope.

69.70 Top of ridge, bears E and W.; descend NE slope.

72.80 Ravine, bears E.; ascend SE slope.

76.10 Top of ridge, bears E and W., descend.

80.00 Set oak stake, 3 ft. long, 5 ins. sq., 24 ins. in the ground for cor. secs. 26, 27, 34 and 35, marked