

## Subdivision of T. 28.S., R. 2 W.

CHAINS

E face, from which

A fir, 10 ins. diam., bears S.5\*W., 23 lks. dist.,  
marked  $\frac{1}{4}$  S 15 B T.

A fir, 10 ins. diam., bears N.85\*E., 30 lks. dist.,  
marked  $\frac{1}{4}$  S 14 B T.

Descend NW slope.

47.50 Ravine, bears W.; ascend NW slope.

58.00 Trail, bears NW and SE.

80.00 Set cedar post, 3 ft. long, 4 ins. sq., 24 ins. in the  
ground for cor. secs. 10, 11, 14 and 15, marked  
T 28 S S 11 on NE., R 2 W S 14 on SE., S 15 on SW.,  
and S 10 on NW., with 4 notches on S and 2 notches  
on E edge, from which

A fir, 10 ins. diam., bears N.70\*E., 35 lks. dist.,  
marked T 28 S R 2 W S 11 B T.

A hemlock, 5 ins. diam., bears S.45\*E., 20 lks. dist.,  
marked T 28 S R 2 W S 14 B T.

A hemlock, 36 ins. diam., bears S.59\*W., 44 lks.  
dist., marked T 28 S R 2 W S 15 B T.

A hemlock, 24 ins. diam., bears N.12\*W., 15 lks.  
dist., marked T 28 S R 2 W S 10 B T.

Land, mountainous.

Soil, rocky; 4th rate.

Timber, cedar, fir, pine and hemlock.

Underbrush, rhododendrons, willows, young firs, vine  
maple and greasewood.

Land mountainous, covered with dense underbrush and  
heavily timbered and exceptionally difficult to  
survey, 80.00 chs.

September 17, 1909

Thence I run

N.3'E., on true line, bet. secs. 10 and 11.