

Subdivision of T. 28 S., R. 2 W.

CHAINS	
	Through dense underbrush and heavy timber; descend NW slope.
25.80	Bottom of ravine, bears W.; ascend S slope.
30.40	Top of ridge, bears E and W.; descend N slope.
32.00	Creek, 2 lks. wide, flows W.; ascend SW slope.
40.00	Set granite stone, 8x12x14 ins., 10 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on W face, from which <div style="margin-left: 40px;">A yew, 12 ins. diam., bears N.63*W., 15 lks. dist., marked $\frac{1}{4}$ S 9 B T. A fir, 5 ins. diam., bears N.55*E., 16 lks. dist., marked $\frac{1}{4}$ S 10 B T.</div>
47.20	Top of ridge, bears E and W.; descend N slope.
64.00	Trail, bears NW and SE.
75.20	Cavite Creek, bears W.; ascend S slope.
80.00	Set fir post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for cor. secs. 3, 4, 9 and 10, marked T 28 S S 3 on NE., R 2 W S 10 on SE., S 9 on SW., and S 4 on NW., face, with 3 notches on E and 5 notches on S edge, from which <div style="margin-left: 40px;">A fir, 8 ins. diam., bears N.30*E., 45 lks. dist., marked T 28 S R 2 W S 3 B T. A willow, 6 ins. diam., bears S.17*E., 21 lks. dist., marked T 28 S R 2 W S 10 B T. A fir, 12 ins. diam., bears S.22*W., 57 lks. dist., marked T 28 S R 2 W S 9 B T. A fir, 8 ins. diam., bears N.78*W., 18 lks. dist., marked T 28 S R 2 W S 4 B T.</div>
	Land, mountainous.
	Soil, rocky; 4th rate.
	Timber, cedar, fir and hemlock.
	Underbrush, rhododendrons, vine maple, greasewood and young firs.
	Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey.
	80.00 chs.

June 20, 1910.