

## County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 28 S., R. 2 W.

CHAINS

Thence I run

N.89°59'E., on random line, bet. secs. 21 and 28.

40.00 Set temp.  $\frac{1}{4}$  sec. cor.80.02 Intersect N and S line, 5 lks. N of cor. secs. 21, 22,  
27 and 28.

Thence I run

N.89°59'W., on true line, bet. secs. 21 and 28 through  
dense underbrush and heavy timber.

6.00 Descend S W slope.

18.90 Creek, 3 lks. wide, flows NW.; ascend SE slope.

31.00 Top of ridge, bears N and S.; descend SW slope.

40.01 Set hemlock stake, 3 ft. long, 4 ins. sq., 24 ins. in  
the ground for  $\frac{1}{4}$  sec. cor., marked  $\frac{1}{4}$  S 21 on N and  
28 on S face, from whichA cedar, 10 ins. diam., bears S.14°E., 16 lks.  
dist., marked  $\frac{1}{4}$  S 28 B T.A hemlock, 7 ins. diam., bears N.21°W., 13 lks.  
dist., marked  $\frac{1}{4}$  S 21 B T.

45.00 Creek, 6 lks. wide, flows N.; ascend E slope.

48.00 Top of ridge, bears N and S.; descend NW slope.

54.60 Creek, 2 lks. wide, flows N.; ascend E slope.

56.00 Top of ridge, bears N and S.; descend NW slope.

58.20 Ravine, bears NW.; ascend NE slope.

64.00 Top of ridge, bears N and S.; descend NW slope.

70.00 Ridge, bears NE and SW.; descend NW slope.

80.02 Cor. secs. 20, 21, 28 and 29.

Land, mountainous.

Soil, rocky; 4th rate.

Timber, cedar, fir and hemlock.

Underbrush, vine maple, rhododendrons, willows and  
young firs.Land mountainous, covered with dense underbrush and  
heavily timbered and exceptionally difficult to  
survey, 80.02 chs.

September 13, 1909.