

Subdivision of T. 28 S., R. 2 W.

CHAINS

Underbrush, greasewood, young firs, willows and rhododendrons.

Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey, 80.00 chs.

Thence I run

N.89*40'E., on random line, bet. secs. 9 and 16.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

80.22 Intersect 23 lks. N of cor. secs. 9, 10, 15 and 16.

Thence I run

S.89*50'W. on true line, bet. secs. 9 and 16; through dense underbrush and heavy timber.

Descend NW slope.

13.70 Middle fork Cavite Creek, 10 lks. wide, flows N.; ascend NE slope.

34.00 Top of ridge, bears N and S.; descend N slope.

40.11 Set granite stone, 6x8x14 ins., 10 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on N. face, from which
 A fir, 6 ins. diam., bears S.50*E., 12 lks. dist., marked $\frac{1}{4}$ S 16 B T.
 A fir, 10 ins. diam., bears N.53*E., 19 lks. dist., marked $\frac{1}{4}$ S 9 B T.

48.00 Ravine, bears N.; ascend SE slope.

54.00 Top of ridge, bears N and S.; descend NW slope.

75.20 Cavite^t Creek, 5 lks. wide, flows N.; ascend NE slope.

78.50 Top of ridge, bears N and S.; descend W slope.

80.22 Cor. secs. 8, 9, 16 and 17.

Land, mountainous.

Soil, rocky; 3d rate.

Timber, cedar, fir and hemlock.

Underbrush, willows, young firs and rhododendrons.

Land, mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to