

## County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 28 S., R. 2 W.

CHAINS

heavily timbered and exceptionally difficult to survey, 80.16 chs.

June 24, 1910.

Thence I run

N.2'E., on true line, bet. secs. 4 and 5.

Through dense underbrush and heavy timber; ascend S slope.

40.00 Set granite stone, 8x10x12 ins., 8 ins. in the ground for  $\frac{1}{4}$  sec. cor., marked  $\frac{1}{4}$  on W face, from which

A fir, 8 ins. diam., bears S.5'E., 34 lks.

dist., marked  $\frac{1}{4}$  S 4 B T.

A laurel, 5 ins. diam., bears N.15'W., 62 lks.

dist., marked  $\frac{1}{4}$  S 5 B T.

74.91 Intersect 6th Standard Parallel, 150 lks. W of cor. secs. 32 and 33.

Set fir post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for closing cor. secs. 4 and 5, marked

C C T 28 S R 2 W on S., S 4 on E and S 5 on W face,

with 4 grooves on E and 2 grooves on W face, from which

A chinquapin, 10 ins. diam., bears S.17'E., 21 lks.

dist., marked T 28 S R 2 W S 4 B T.

A laurel, 12 ins. diam., bears S.68'W., 17 lks.

dist., marked T 28 S R 2 W S 5 B T.

Land, mountainous.

Soil, rocky; 4th rate.

Timber, cedar, fir, matherone and hemlock.

Underbrush, young firs, rhododendrons and willows.

Land mountainous, covered with dense underbrush and

heavily timbered and exceptionally difficult to

survey, 74.91 chs.

June 25, 1910.