

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 28 S., R. 2 W.

CHAINS

80.25 Cor. secs. 29, 30, 31 and 32.

Land, mountainous.

Soil, rocky; 4th rate.

Timber, cedar, fir and hemlock.

Underbrush, rhododendrons, vine maple and willows.

Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey, 80.25 chs.

September 14, 1909.

Thence I run

W., on random line bet. secs. 30 and 31.

40.00 Set temp. $\frac{1}{4}$ sec. cor.80.04 Intersect 2 lks. N of cor. secs. ~~29, 30, 25 and 26~~ ^{30-31-25 & 30}

heretofore described.

Thence I run

N.89°59'E., on true line, bet. secs. 30 and 31, through dense underbrush and heavy timber; descend NE slope.

4.00 Ascend NW slope.

6.00 Descend SE slope.

14.00 Creek, 2 lks. wide, flows SE.; ascend SW slope.

24.00 Top of ridge, bears N and S.; descend SE slope.

34.50 Top of ridge, bears N and S.; descend NE slope.

40.04 Set lava stone, 8x8x12 ins., 8 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on N face, from which

A fir, 5 ins. diam., bears S.6°E., 17 lks.

dist., marked $\frac{1}{4}$ S 31 B T.

A laurel, 5 ins. diam., bears N.50°E., 30 lks.

dist., marked $\frac{1}{4}$ S 30 B T.

47.50 Creek, 2 lks. wide, flows NW.; ascend SW slope.

66.00 Top of ridge, bears N and S.; descend NE slope.

68.00 Ravine, bears N.; ascend NE slope.

70.00 Descend W slope.