

Subdivision of T. 28 S., R. 2 W.

CHAINS	
	<p>A fir, 10 ins. diam., bears N.82*E., 85 lks. dist., marked T 28 S R 2 W S 7 B T.</p> <p>A fir, 24 ins. diam., bears S.60*E., 44 lks. dist., marked T 28 S R 2 W S 18 B T.</p> <p>I destroy markings on other corner and bearing trees referring to secs. 7 and 18.</p> <p>Thence I run</p> <p>N.89*59'E., on true line, bet. secs. 7 and 18; through dense underbrush and heavy timber; descend N slope.</p>
4.00	Ditch, 5 lks. wide, bears NW and SE.
39.90	<p>Set yew post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for <math>\frac{1}{4}</math> sec. cor., marked <math>\frac{1}{4}</math> S 7 on N and 18 on S face, from which</p> <p>A hemlock, 8 ins. diam., bears N.2*W., 6 lks. dist., marked <math>\frac{1}{4}</math> S 7 B T.</p> <p>A hemlock, 8 ins. diam., bears S.23*E., 12 lks. dist., marked <math>\frac{1}{4}</math> S 18 B T.</p>
41.80	Creek, 10 lks. wide, flows N.70*W.; ascend NW slope.
55.60	Top of ridge and Tuttle Trail, bears N and S.; descend NE slope.
62.30	Ravine, bears N.; ascend NW slope.
72.00	Top of ridge, bears N and S.; descend E slope.
77.00	Ravine, bears N.; ascend NW slope.
79.90	Cor. secs. 7, 8, 17 and 18.
	<p>Land, mountainous:</p> <p>Soil, rocky; 4th rate.</p> <p>Timber, cedar, fir, yellow pine and hemlock.</p> <p>Underbrush, rhododendrons, vine maple, young firs, greasewood and willows.</p> <p>Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey.</p> <p>79.90 chs.</p>
	Thence I run