

Subdivision of T. 28 S., R. 2 W.

CHAINS

N.1'E., on true line, bet. secs. 7 and 8, through dense underbrush and heavy timber; descend N slope.

16.70 Creek, 1 lk. wide, flows E.

32.00 Trail, bears E and W.

32.37 Cavite⁺ Creek, 30 lks. wide, flows N.56*W.

33.70 Trail, bears E and W.; ascend S slope.

40.00 Set cedar stake, 3 ft. long, 4 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S 7 on W and 8 on E face, from which

A laurel, 8 ins. diam., bears S.80*E., 26 lks. dist., marked $\frac{1}{4}$ S 8 B T.

A fir, 15 ins. diam., bears S.70*W., 25 lks. dist., marked $\frac{1}{4}$ S 7 B T.

68.00 Top of ridge, bears E and W.; descend NW slope.

80.00 Set granite stone, 10x12x20 ins., 15 ins. in the ground for cor. secs. 5, 6, 7 and 8, marked with 5 notches on E and 4 notches on S edge, from which

An oak, 8 ins. diam., bears N.60*E., 89 lks. dist., marked T 28 S R 2 W S 5 B T.

A laurel, 8 ins. diam., bears S.70*E., 86 lks. dist., marked T 28 S R 2 W S 8 B T.

A laurel, 10 ins. diam., bears S.20*W., 66 lks. dist., marked T 28 S R 2 W S 7 B T.

A laurel, 7 ins. diam., bears N.40*W., 70 lks. dist., marked T 28 S R 2 W S 6 B T.

Land, mountainous.

Soil, rocky; 4th rate.

Timber, cedar, fir, hemlock and yellow pine.

Underbrush, rhododendrons, vine maple, young firs and willows.

Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey, 80.00 chs.

June 29, 1910.