

36  
County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 28 S., R. 2 W.

CHAINS

C C T 28 S R 2 W on E., S 6 on N., and S 7 on S face,  
with 1 groove on N and 5 grooves on S face, from which

A cedar, 16 ins. diam., bears N.82°E., 48 lks.

dist., marked T 28 S R 2 W S 6 B T.

A cedar, 16 ins. diam., bears S.20°E., 82 lks.

dist., marked T 28 S R 2 W S 7 B T.

I destroy markings on other corner and bearing trees re-  
ferring to secs. 6 and 7.

Thence I run

N.89°59'E., on true line, bet. secs. 6 and 7.

Through dense underbrush and heavy timber; ascend SW slope.

39.90 Set granite stone, 12x12x14 ins., 10 ins. in the ground  
for  $\frac{1}{4}$  sec. cor., marked  $\frac{1}{4}$  on N face, from which

A laurel, 18 ins. diam., bears N.40°W., 32 lks.

dist., marked  $\frac{1}{4}$  S 6 B T.

A fir, 10 ins. diam., bears S.60°E., 22 lks.

dist., marked  $\frac{1}{4}$  S 7 B T.

58.00 Descend SE slope.

66.00 Creek, 4 lks. wide, flows S.; ascend SW slope.

79.90 Cor. secs. 5, 6, 7 and 8.

Land, mountainous.

Soil, rocky; 4th rate.

Timber, fir, cedar, yellow pine and hemlock.

Underbrush, rhododendrons, vine maple and young firs.

Land, mountainous, covered with dense underbrush and  
heavily timbered and exceptionally difficult to  
survey, 79.90 chs.

June 30, 1910.

Thence I run

N.1°E., on true line, bet. secs. 5 and 6, through

dense underbrush and heavy timber; ascend S slope.

32.00 Top of ridge, bears E and W.; descend N slope.