

Retracement and Resurvey of Subdivisions of
T. 28 S. R. 2 W.

CHAINS	
	<p style="text-align: center;">¼ S 23 1923</p> <p style="text-align: right;">from which</p> <p>A fir, 14 ins. diam., bears N.54*E., 12 lks. dist., marked ¼ S 23 B T.</p> <p>A fir, 22 ins. diam., bears S.87*E., 23 lks. dist., marked ¼ S 23 B T.</p>
23.28	Brook, 3 lks. wide, course NW.; ascend 70 feet over SW slope.
28.60	Spur, slopes NW.; descend 150 feet, over NE slope.
39.81	<p>The cor. established for secs. 14, 15, 22 and 23, which is a fir post, 12x4x4 ins. above ground, firmly set, marked T 28 S S 15 on NW.; R 2 W S 22 on SW.; face, with 3 notches on S and 2 notches on E edge.</p> <p>Hereafter, this cor. will refer to secs. 15 and 22 only. No marks are found on NE and SE faces; from the corner</p> <p style="padding-left: 40px;">A fir, 20 ins. diam., bears S.69*W., 29 lks. dist., marked T 28 S R 2 W S 22 B T; old bearing tree.</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears N.39*W., 16 lks. dist., marked T 28 S R 2 W S 15 B T; old bearing tree.</p> <p style="padding-left: 40px;">The original bearing tree, in sec. 14, not found.</p> <p>Land, mountainous.</p> <p>Soil, clay loam; 2d and 3d rate.</p> <p>Timber, fir, hemlock and cedar.</p> <p>Undergrowth, rhododendron, chinquapin, vine maple and hemlock.</p>
39.88 79.98	<p>N.0*3'E., retracing bet. secs. 14 and 15. The ¼ sec. cor., bears E 13 lks. dist. Fall 28 lks. W of the cor. of secs. 10, 11, 14 and 15.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>From the cor. of secs. 15 and 22.</p> <p>N.0*14'E., resurveying the E bdy. of sec. 15.</p> <p>Over mountainous land, through heavy timber and dense</p>