

Retracement and Resurvey of Subdivisions of
T. 28 S., R. 2 W.

CHAINS

A cedar, 8 ins. diam., bears N.59*E., 25 lks.
dist., marked $\frac{1}{4}$ S 14 B T.

A hemlock, 5 ins. diam., bears S.67*E., 24 lks.
dist., marked $\frac{1}{4}$ S 14 B T.

4.50 Spur, slopes NW.; descend 325 feet.

11.40 Enter old burn, bears E and W.

17.50 Flat spur, slopes NW.

22.15 Leave old burn, bears E and W.

40.10 The cor. established for secs. 10, 11, 14 and 15 which
is a cedar post, 12x4x4 ins. above ground, firmly
set, in good condition marked T 28 S S 10 on NW
and R 2 W., S 15 on SW face. Hereafter this corner
will refer to secs. 10 and 15 only. No marks are
found referring to secs. 11 and 14, and no bearing
trees are found east of line as shown in the field
notes; from the corner

A hemlock, 36 ins. diam., bears S.59*W., 15 lks.
dist., marked T 28 S R 2 W S 15 B T; old
bearing tree.

A hemlock, 24 ins. diam., bears N.12*W., 44 lks.
dist., marked T 28 S R 2 W S 10 B T; old
bearing tree.

Land, mountainous.

Soil, clay loam; 2d and 3d rate.

Timber, fir, hemlock and cedar.

Undergrowth, rhododendron, chinquapin, vine maple and
hemlock.

40.16 N.0*3'E., retracing bet. secs. 10 and 11.
80.31 The $\frac{1}{4}$ sec. cor. bears W 27 lks. dist.
Fall 45 lks. E of the cor. of secs. 2, 3, 10 and 11.

From the cor. of secs. 10 and 15.

N.0*20'W., resurveying the E bdy. of sec. 10.