

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 28 S., R. 2 W.

CHAINS	
	<p>dist., marked $\frac{1}{4}$ S 11 B T.</p> <p>A hemlock, 30 ins. diam., bears S.50*W., 63 lks. dist., marked $\frac{1}{4}$ S 14 B T.</p> <p>Descend 40 feet to</p>
41.83	Creek, 8 lks. wide, course NW
48.52	Brook, 1 lk. wide, course SW.; ascend 70 feet to
56.60	Spur, slopes N.; descend 50 feet to
62.63	Creek, 5 lks. wide, course NW.; ascend 300 feet to
77.22	The cor. of secs. 11, 12, 13 and 14.
	<p>Land, mountainous.</p> <p>Soil, clay loam; 2d and 3d rate.</p> <p>Timber, fir, cedar, hemlock and pine.</p> <p>Undergrowth, rhododendron, chinquapin, vine maple and hemlock.</p>
	<p>North on a Sectional Guide Meridian bet. secs. 11 and 12.</p> <p>Over mountainous land, through heavy timber and dense undergrowth.</p> <p>Descend 320 feet over NW slope.</p>
2.00	Spur, slopes NW.
17.03	Creek, 8 lks. wide, course NW.
29.26	Creek, 17 lks. wide, course SW.; ascend 60 feet to spur.
34.45	Brook, 2 lks. wide, course SW.
36.50	Spur, slopes SW.; descend gradually over NW slope.
40.00	Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked
	<p>from which</p> <p>A fir, 7 ins. diam., bears S.58*E., 12 lks. dist., marked $\frac{1}{4}$ S 12 B T.</p> <p>A fir, 8 ins. diam., bears N.40*W., 11 lks. dist., marked $\frac{1}{4}$ S 11 B T.</p>