

Subdivision of T. 28 S. R. 3 W.

CHAINS	
	N. on true line bet. secs. 14 and 15. Va. 19* E.
	Descend Mountain
40.00	Set cedar post, 3 ft. long, 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S. on E. and W. faces, from which: <ul style="list-style-type: none"> A Fir, 36 ins. diam., bears S.25*W., 5 lks. dist. marked $\frac{1}{4}$ S. B. T. A Fir, 6 ins. diam., bears S.70*E., 17 lks dist. marked $\frac{1}{4}$ S. B. T.
74.20	Stream, 4 lks wide, Course N. E.
74.25	Ascend Steep Hill
79.50	Summit of Hill.
80.00	Set Laurel post, 4 ft. long, 4 ins. sq., 24 ins. in the ground for cor. to secs., 10,11,14 and 15, marked T 28 S S.11 on N. E., R 3 W S 14 on S. E., S.15 on S.W. and S 10 on N. W. faces with 2 notches on E. and 4 on the S. edges, from which: <ul style="list-style-type: none"> A Laurel, 8 ins. diam., bears N.15*E., 32 lks dist. marked T 28 S R 3 W S 11 B. T. A Laurel, 7 ins. diam., bears S.75*E., 23 lks dist. marked T 28 S R. 3 W S 14 B. T. A Fir, 20 ins. diam., bears S.65*W., 54 lks dist. marked T 28 S R 3 W S 15 B. T. A Fir, 36 ins. diam., bears N.45*W.,17 lks dist. marked T 28 S R 3 W S 10 B. T. <p>This mile is rough and hilly land- 3rd. rate. Densely covered with forests of Fir, Cedar, Hemlock and Laurel- Thick undergrowth of Fir, Vine Maple and Hazel.</p> <p style="text-align: right;">Sept. 20th, 1882.</p>
	E. on random line bet. secs. 11 and 14. Va. 19*E.
7.50	Stream, 6 lks wide, Course N. E.
9.95	Stream, 4 lks wide, Course N. W.
37.10	Summit of Mountain.