

## Subdivisions of T.28 S.R. 3 W.

CHAINS

Timber, fir, cedar, hemlock and matherone.

Underbrush, young firs, rhododendrons and willows.

Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey.

May 25, 1910.

At Cor. secs. 25, 26, 35 and 36.

Thence I run

South 1'E. on true line bet. secs. 35 and 36, through dense underbrush and heavy timber, descend S.slope.

21.80 Creek, 4 lks. wide, flows SW., ascend W. slope.

40.00 Set granite stone, 6x8x12 ins., 8 ins. in the ground for 1/4 sec. cor., marked 1/4 on W. face, from which:

A fir, 15 ins., diam., bears N.64\*W., 24 lks. dist. marked 1/4 S. 35 B T.

A laurel, 6 ins., diam., bears S.38\*E., 28 lks. dist. marked 1/4 S. 36 B. T.

43.70 Top of ridge and trail, bears SW. and NE., descend S. Slope.

68.30 Creek, 8 lks. wide, flows SW., ascend N. slope.

70.00 Top of ridge, bears E. and W., descend S. Slope.

72.00 Creek, 8 lks. wide, flows W., ascend N. slope.

78.90 Intersect E. and W. lines, 96 lks. W. from N 1/4 Sec. cor. N. <sup>by</sup> of sec. 1 T 29 S R 3 W.

Set granite stone, 6x8x12 ins., 8 ins. in the ground for closing cor. secs. 35 and 36, marked C C on N. face, with 1 groove on E. and 5 grooves on W. face, from which:

A fir, 30 ins. diam., bears N.67\*E., 45 lks. dist. marked T 28 S R 3 W S 36 B T.

A laurel, 8 ins. diam., bears N. 26\*W., 38 lks dist. marked T 28 S R 3 W S 35 B T.

Land, mountainous.

Soil, rocky, 4th grade

Timber, fir, cedar, hemlock and matherone.