

Subdivisions of T. 28 S.R. 3 W.

CHAINS	
	Underbrush, young firs, rhododendrons and vine maple. Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey.
	From the cor. secs. 25,26,35 and 36, I run North 1' W. on true line bet. secs. 25 and 26, through dense underbrush and scattering timber, ascend S. slope.
14.00	Ascend SW. slope.
35.05	Top of ridge, bears E. and W., descend N. slope.
36.20	Creek, 2 lks. wide, flows W., ascend S. slope.
40.00	Set fir stake, 3 ft. long, 4 ins. sq., 24 ins. in the ground for 1/4 sec. cor. marked 1/4 S 26 on W., and 25 on E. face, from which: A Fir, 14 ins. diam., bears N.80*W., 76 lks dist. marked 1/4 S 26 B T. A fir, 30 ins. diam., bears S.45*E., 49 lks dist. marked 1/4 S 25 B T
51.60	Top of ridge, bears E. and W., descend N. slope.
55.01	Ravine, bears W., leave scattering timber, ascend S slope.
66.96	Morrison and Tuttle trail, bears NW. and SE.
67.55	Top of ridge, bears E. and W., descend NW. slope.
76.00	Enter heavy timber.
80.00	Set granite stone, 6x10x14 ins., 10 ins. in the ground for cor. secs. 23,24,25 and 26, marked with 1 notch on E. and 2 notches on S. edge, from which: A yew, 10 ins. diam., bears N.50*E., 6 lks dist. marked T 28 S R 3 W S 24 B T. A hemlock, 12 ins. diam., bears S.14*E., 23 lks dist. marked T 28 S R 3 W S 25 B T. A hemlock, 6 ins. diam., bears S.50*W., 57 lks dist. marked T 28 S R 3 W S 26 B T.